

The Gallery pages below scroll backward in time.




Through the holidays, we will continue to run the December guided tour video (12 min.)
To watch this video, return to the Building Project home page and click on the image saying "VIRTUAL TOUR"

December 30, 2020

Going on this week:
Work progresses on
final roof details,
exterior masonry,
siding & trim,
mechanical and
electrical rough-ins,
and HVAC ducts.





December 23, 2020

Going on this week:
Work has progressed on roof
shingling, exterior masonry,
siding & trim, and mechanical
and electrical rough-ins. Also
began installing HVAC ducts.


Through the holidays, we will continue to run the December guided tour video (12 min.)
To watch this video, return to the Building Project home page and click on the image saying "VIRTUAL TOUR"







December 17, 2020




Going on this week: Passageways between old building and new building have been broken through (and temporarily covered);
Shingling has begun on roof;
Work continues on exterior siding & trim and on mechanical and electrical rough-ins.

View of future passageway from old building side (on the left) and the new building side (on the right) -Upper Level (above) and Lower Level (below).






This week we again run the December guided tour by video (12 min.) To watch this video, return to the Building Project home page and click on the image saying "VIRTUAL TOUR"



Going on this week: Continue roofing, exterior siding & trim, rough-ins for mechanical/ electrical (plumbing rough-ins passed inspection this week!), prep for hanging drywall.











December 3, 2020

Going on this week: Roof-work; beginning to install exterior siding and trim; continuing to rough-in plumbing/mechanical/electrical; prep framing for hanging drywall.

To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle









November 25, 2020

To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the

middle

Going on this
week: Tyvek
weather-proofing;
plumbing,
mechanical and
electrical roughins; prep roof for
shingling; roughgrading site







Alcove door

Views from N side of site: Porch and Gallery in foreground.

To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle

November 19, 2020

Going on this
week: Framing;
rough-ins for
plumbing,
mechanical and
electrical installations







To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle

November 12, 2020

Going on this week: Roofing underlayment, wall sheathing, upstairs interior wall studs





Views from N side of site, looking at Multi-Purpose Room with Gallery and Porch in foreground





To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle

November 3-5, 2020

Going on this week: Framing rises to the top!



View from playground: Multi-Purpose Room above, Living Room below For earlier photos, return to base page and click on Photo Gallery "IIA" for Jan-Jun 2020, "IIB" for Jul-Aug 2020, or "IIC" for Sep-Oct 2020