


The Gallery pages below scroll backward in time.



While the workers continue to address "punch list" items as they finish up the new wing of the Jones Building, our webpage photojournalist team is away on vacation...















June 17, 2021



To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.

Going on this week:

Continuing to check off the "punch list" items on way to finishing up

South-facing exterior, from three different angles, in the light of the setting sun





In Gallery, the main entrance to Gathering Room (in left background, doorway from old Jones)





In Gathering Room just inside main entrance Looking toward south wall

To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.



June 10, 2021

Going on this week:

Looking good! Punch list items have been agreed upon, and necessary adjustments and finishing details are in progress.



In Gathering Room (Looking toward north wall with main entrance)



In Living Room on lower level Looking toward south wall (entrance door in far left corner)



In Living Room on lower level Looking from entrance door toward north wall



Mystery Railing: last week painted and ready to go... where?

Here!

(at foot of stairs to lower level)



To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.

June 4, 2021

Going on this week:

Though the premises LOOK ready, numerous details still must be completed before the building is "in service" - Stay tuned!



View across south wall of upper level (Gathering Room) to west corner (note stained natural wood windowsill)



Paved, freshly marked parking by church office





To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.

May 27, 2021

Going on this week:


Further staining and varnishing natural wood trim; Beautiful stairs; Plenty of railings; Lots of details...










Mystery Railing: all painted and ready to go... where?
(Look again next week for the answer)








Steps to Gathering Room




Steps From Gallery, beside Lift



Landing at foot of Stairway to Lower Level



Suspended podium lights in Gathering Room



Welder at work: Railing for back porch

May 20, 2021

Going on this week:

Continue staining and installing the wood trim; Other finishing details everywhere you look!

To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.



A door opener!


May 11-13, 2021



To see this week's video of the construction site, return to Building Project home page and click on photo with this symbol in the middle.

Going on this week:

Staining and installing the wood trim (e.g. kick boards around the walls, stairways);
Staining and polishing the Gallery's concrete floor; repairing the old paving in front and back lots.













week

the Gathering Room!

Going on this With plumbing and other messy installations largely done, SURPRISE - In one day, carpeting tiles transform the floors of the Living Room and

To see this week's video of the construction site, return to **Building Project** home page and click on photo with this symbol in the middle.

Lower Level: The Living Room



For earlier photos, return to base page and click on Photo Gallery "II-A" for Jan-Jun 2020, "II-B" for Jul-Aug 2020, "II-C" for Sep-Oct 2020, "II-D" for Nov-Dec 2020, "II-E" for Jan-Feb 2021, or "II-F" for Mar-Apr 2021